Roads, Vehicles & Equipment

Safety Alert Airbridge Struck Mobile GPU

10 March 2023

ASGrOps_SA_048

V1.0

S

1. Introduction

On the 1st of March an airbridge was being manoeuvred towards the door of an A321 that had recently arrived on stand, when the port-side of the airbridge wheel bogie collided with an incorrectly parked portable GPU that had been left within the stand footprint.

The airbridge operator was aware of the presence of the GPU prior to commencing their manoeuvre and believed they could navigate the obstacle.



2. Safety Considerations

- Perform a full visual check of the intended path of movement to check for obstacles prior to manoeuvring the airbridge. Do not rely solely on the cameras
- Should any obstacles or GSE pose a potential collision risk, ensure this is moved by a suitably trained person prior to commencing a maneouvre

Enquiries

Any questions regarding this Safety Alert should be addressed to airside_safety@heathrow.com Additional information, Operational Safety Instructions (OSIs) and Operational Advice Notices (OANs) can be found at <u>heathrow.com/airside/useful-publications</u>

Reference:

Author: Amber Avis Job title: Airside Safety Investigation Officer Location: Airside Operations Facility Effective date: 10 March 2023 Approved by: Alex Bailey Job title: Airside Safety Investigation Manager





www.heathrow.com/airside